



usdigital.com
 1400 NE 136th Ave.
 Vancouver, WA 98684
 Local: 360.260.2468
 Sales: 800.736.0194

Product Change Notification

PCN-5367_HUBS

USD-5367

Date of Notification	Change		Part Numbers Affected
July 20, 2015	<input type="checkbox"/> Major	<input checked="" type="checkbox"/> Minor	A2K, E2, E3, E5, E6, HUBDISK-1, HUBDISK-2

Notification

<input type="checkbox"/> Product Obsolescence	<input type="checkbox"/> Product Marking	<input checked="" type="checkbox"/> Process Change	<input type="checkbox"/> Design Change
<input type="checkbox"/> Material Change	<input type="checkbox"/> Specification Change	<input type="checkbox"/> Component Change	<input type="checkbox"/> Other

Notification Description (Including Extent, Purpose / Reason, and Effect on Form, Fit and Function)

As part of our ongoing continuous improvement efforts, US Digital is implementing a change related to the production of our 5/16" (.313), 8mm (.315), 3/8" (.375), and 10mm (.394) HUBDISK assemblies. We are adding a low strength threadlocker to the set screw during our assembly process to assist in securing the set screw in the hub during transportation. This will aid in the set screw retention of these specific hub sizes; ensuring the retention is sufficient and avoid the potential of them backing out of the hub assembly during transit. This change does not affect form, fit or function.

If you have any questions or concerns about this PCN, please contact our Technical Support Group at 360-397-9999 or email support@usdigital.com.

Alternate Parts (as applicable)

N/A

Effective Date (Including Last Time Buy Date and Conditions, as applicable)

This change is effective for all shipments made on or after July 20, 2015